



Essex County
Fire & Rescue Service

Extract Copy of Fire Report

Details At Call

Incident Number:	██████████
Time of Call:	██████████/2017 11:12:22 PM
Incident Type at Control:	Fire - Building
Late Call:	No
Station Groud of Incident:	Rayleigh Weir
Time of Stop Message:	██████████/2017 12:13:33 AM
Time Incident Closed:	██████████/2017 1:34:22 AM

Details At Attendance

Incident Type:	Fire
Property Type:	Property/Building/Dwelling/House - single occupancy
Persons Rescued, Extricated, or Killed:	No
Persons Evacuated:	Yes
Pumping Appliances Deployed Before Mobilising Stopped:	2

Incident Location

Building Name / Number:	██
Street:	██████████ ██████████
Town:	BENFLEET
Post Code:	██████████



Essex County
Fire & Rescue Service

Extract Copy of Fire Report

Additional Information

Fire Multiple Seated:	No
Ignition to Discovery Time:	Over 30 minutes and up to 2 hours
Discovery to First Call Time:	Immediately
How was the Fire Discovered:	Person
Do Fire Regulations Apply:	No
Alarm System Present:	No
Anyone in Building at Time of Fire:	Yes
Is the Building Normally Occupied:	Yes - occupied
Cause/Motive:	Accidental
Hazmats Involved:	No

Action

Delay in Commencing Fire Fighting Actions:	No delay
Main Action Taken by Public Prior to Arrival:	None
Main Action Taken by FRS Personnel:	Hosereel (high pressure) (HRJ) - tank supply only
Manual Systems Used:	No
Active Safety Systems Present:	No



Essex County Fire & Rescue Service

Extract Copy of Fire Report

Damage	
Cause of the Fire:	Fault in equipment or appliance
Make and Model:	Electric blanket
Source of Ignition:	Electricity supply - Wiring, cabling, plugs
Ignition Powered by:	Electric
First Item Ignited:	Electric blanket
Item Mainly Responsible for Spread:	Furniture/Furnishings - Bed/Mattress
Rapid Fire Growth Cause:	No rapid fire growth
Dangerous Substances Involved:	None
Explosion Involved:	No
Location of Origin:	Bedroom
Household Occupancy Type:	Couple one or more over pensionable age, no child/ren
Contributing Human Factors:	None
Was Impairment due to Suspected Drugs/Alcohol a Contributory Factor in the Fire:	No
Special Method of Building Construction:	None
Only Heat and Smoke Damage:	No
Distance to Adjacent Properties Affected at Time Arrived:	No other property affected
Distance to Adjacent Properties Affected at time of Stop:	No other property affected
Fire Damaged Area at Stop:	11 - 20
Total Damaged Area at Stop:	201 - 500

Additional Information

Section 10.4:

The owners returned from holiday. They put the electric blanket on and the proceeded to the lounge. After a period of time approx. 1 hour they noticed smoke and evacuated the property.

Signed:

A handwritten signature in black ink, appearing to be 'AT' or similar initials.

Ana M Tuckwell |
Information Governance Manager & Deputy DPO Systems and Data Department

Date: 23/02/2023